

CERTIFICATE OF COMPLIANCE

Certificate Number E313491
Report Reference E313491-20200814
Date 2023-September-04

Issued to: Chint New Energy Technology Co., Ltd.
No 1 Jisheng Road, Jianshan New District
Haining Zhejiang Sheng 314415 CN

This is to certify that representative samples of PHOTOVOLTAIC MODULES AND PANELS WITH SYSTEM VOLTAGE RATINGS OVER 600 VOLTS
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: See Addendum Page

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.


Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E313491
Report Reference E313491-20200814
Date 2023-September-04

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

UL 61730-1, Photovoltaic (PV) Module Safety Qualification - Part 1: Requirements for Construction, and UL 61730-2, Photovoltaic (PV) Module Safety Qualification - Part 2: Requirements for Testing.

International Standard for CAN/CSA-C22.2 No. 61730-1: December 2019, Photovoltaic (PV) module safety qualification — Part 1: Requirements for construction and CAN/CSA-C22.2 No. 61730-2: Photovoltaic (PV) module safety qualification — Part 2: Requirements for testing.

USL/CNL - Photovoltaic Module, Models:

Module series with 166 half-cut cells:

CHSM78M-HC-480, CHSM78M-HC-485, CHSM78M-HC-490, CHSM78M-HC-495, CHSM78M-HC-500

CHSM72M-HC-425, CHSM72M-HC-430, CHSM72M-HC-435, CHSM72M-HC-440, CHSM72M-HC-445,
CHSM72M-HC-450, CHSM72M-HC-455
CHSM72M-GH-420, CHSM72M-GH-425, CHSM72M-GH-430, CHSM72M-GH-435, CHSM72M-GH-440,
CHSM72M-GH-445, CHSM72M-GH-450,

CHSM66M-HC-410, CHSM66M-HC-415, CHSM66M-HC-420

CHSM60M-HC-355, CHSM60M-HC-360, CHSM60M-HC-365, CHSM60M-HC-370, CHSM60M-HC-375,
CHSM60M-HC-380,
CHSM60M-GH-350, CHSM60M-GH-355, CHSM60M-GH-360, CHSM60M-GH-365, CHSM60M-GH-370,
CHSM60M-GH-375,


Module series with 158.75 half-cut cells:

CHSM60M-HC-325, CHSM60M-HC-330, CHSM60M-HC-335, CHSM60M-HC-340, CHSM60M-HC-345,
CHSM60M-HC-350

CHSM60M-GH-320, CHSM60M-GH-325, CHSM60M-GH-330, CHSM60M-GH-335, CHSM60M-GH-340,
CHSM60M-GH-345

CHSM60M-TH-320, CHSM60M-TH-325, CHSM60M-TH-330, CHSM60M-TH-335, CHSM60M-TH-340,
CHSM60M-TH-345

CHSM72M-HC-390, CHSM72M-HC-395, CHSM72M-HC-400, CHSM72M-HC-405, CHSM72M-HC-410,
CHSM72M-HC-415, CHSM72M-HC-420,


Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E313491
Report Reference E313491-20200814
Date 2023-September-04

CHSM72M-GH-385, CHSM72M-GH-390, CHSM72M-GH-395, CHSM72M-GH-400, CHSM72M-GH-405, CHSM72M-GH-410, CHSM72M-GH-415,

CHSM72M-TH-385, CHSM72M-TH-390, CHSM72M-TH-395, CHSM72M-TH-400, CHSM72M-TH-405, CHSM72M-TH-410, CHSM72M-TH-415

Module series with 182 half-cut cells:

*CHSM54M-HC-390, CHSM54M-HC-395, CHSM54M-HC-400, CHSM54M-HC-405, CHSM54M-HC-410, CHSM54M-HC-415

CHSM54M-GH-390, CHSM54M-GH-395, CHSM54M-GH-400, CHSM54M-GH-405

CHSM72M-GH-515, CHSM72M-GH-520, CHSM72M-GH-525, CHSM72M-GH-530, CHSM72M-GH-535, CHSM72M-GH-540, CHSM72M-GH-545

CHSM72M-HC-520, CHSM72M-HC-525, CHSM72M-HC-530, CHSM72M-HC-535, CHSM72M-HC-540, CHSM72M-HC-545, CHSM72M-HC-550,

CHSM66M-HC-475, CHSM66M-HC-480, CHSM66M-HC-485, CHSM66M-HC-490, CHSM66M-HC-495, CHSM66M-HC-500, CHSM66M-HC-505.

CHSM78M-HC-565, CHSM78M-HC-570, CHSM78M-HC-575, CHSM78M-HC-580, CHSM78M-HC-585, CHSM78M-HC-590, CHSM78M-HC-595, CHSM78M-HC-600, CHSM78M-HC-605

CHSM60M-HC-430, CHSM60M-HC-435, CHSM60M-HC-440, CHSM60M-HC-445, CHSM60M-HC-450, CHSM60M-HC-455, CHSM60M-HC-460

Module series with 210 half-cut cells:

CHSM66M-HC-645, CHSM66M-HC-650, CHSM66M-HC-655, CHSM66M-HC-660, CHSM66M-HC-665, CHSM66M-HC-670, CHSM66M-HC-675

CHSM60M-HC-585, CHSM60M-HC-590, CHSM60M-HC-595, CHSM60M-HC-600, CHSM60M-HC-605, CHSM60M-HC-610, CHSM60M-HC-615

*CHSM55M-HC-530, CHSM55M-HC-535, CHSM55M-HC-540, CHSM55M-HC-545, CHSM55M-HC-550, CHSM55M-HC-555, CHSM55M-HC-560, CHSM55M-HC-565

*CHSM50M-HC-480, CHSM50M-HC-485, CHSM50M-HC-490, CHSM50M-HC-495, CHSM50M-HC-500, CHSM50M-HC-505, CHSM50M-HC-510, CHSM50M-HC-515

Module series with 210 half-cut Topcon cells:

CHSM66N-HC-655, CHSM66N-HC-660, CHSM66N-HC-665, CHSM66N-HC-670, CHSM66N-HC-675, CHSM66N-HC-680, CHSM66N-HC-685, CHSM66N-HC-690, CHSM66N-HC-695

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E313491
Report Reference E313491-20200814
Date 2023-September-04

CHSM60N-HC-595, CHSM60N-HC-600, CHSM60N-HC-605, CHSM60N-HC-610, CHSM60N-HC-615, CHSM60N-HC-620, CHSM60N-HC-625, CHSM60N-HC-630, CHSM60N-HC-635.

Module series with 182 half-cut Topcon cells:

CHSM78N-HC-585, CHSM78N-HC-590, CHSM78N-HC-595, CHSM78N-HC-600, CHSM78N-HC-605, CHSM78N-HC-610, CHSM78N-HC-615, CHSM78N-HC-620, CHSM78N-HC-625

CHSM72N-HC-550, CHSM72N-HC-555, CHSM72N-HC-560, CHSM72N-HC-565, CHSM72N-HC-570, CHSM72N-HC-575

CHSM60N-HC-450, CHSM60N-HC-455, CHSM60N-HC-460, CHSM60N-HC-465, CHSM60N-HC-470, CHSM60N-HC-475, CHSM60N-HC-480

CHSM54N-HC-405, CHSM54N-HC-410, CHSM54N-HC-415, CHSM54N-HC-420, CHSM54N-HC-425, CHSM54N-HC-430, CHSM54N-HC-435

Module series with 182*191 half-cut Topcon cells:

CHSM72RN-HC-590, CHSM72RN-HC-595, CHSM72RN-HC-600, CHSM72RN-HC-605, CHSM72RN-HC-610, CHSM72RN-HC-615, CHSM72RN-HC-620

CHSM54RN-HC-450, CHSM54RN-HC-455, CHSM54RN-HC-460, CHSM54RN-HC-465

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

